

City of Columbus Source Water Monitoring

		Dublin Road Water Plant Source Water		Hap Creaman Water Plant Source Water		Parsons Avenue Water Plant Source Water	
Contaminant	Proposed MCL	Level Found	Range	Level Found	Range	Level Found	Range
PFOA	4 ppt	3.7 ppt	ND - 6.3 ppt	ND	ND	ND	ND
PFOS	4 ppt	2.6 ppt	ND - 5.6 ppt	ND	ND	ND	ND
PFBS	Health Index = 1	0.002	ND - 16.2 ppt	ND	ND	ND	ND
PFHxS			ND		ND		
PFNA			ND		ND		
GenX			ND		ND		

ND = Non-Detect below the method detection limit of 4 ppt

Level Found = Running Annual Average calculated per proposed PFAS regulation